# Weathertzation Assistance Program

# Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

*Work Order Name:* WO/15015SE-4179/1

Work Order Type: Weatherization

Audit Name: NA

**CLIENT INFORMATION** 

Client Name: Address:

*Client ID:* 15015SE-4179

Alt. Client ID: McMinn

<u>AGENCY INFORMATION</u>

Agency: Southeast Tennessee Human Resource Agency Agency Phone: (423) 949-2191

**Address:** 312 Resource Rd. **Fax:** (423) 949-4023

Agency Contact: Gaskins, Glenn Work Phone:

*Cell Phone:* (865) 679-8303

Email Address: amerispechome20@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

## **COMMENT**

Site Built Home

Home was built pre-1978. Lead Safe Weatherization protocol required.

# **Measures**

Measure 1 CO Monitor is Needed			Components					Inspected	
	Attachment A- Standard ast Field Guide.	s for Wea	atheriza	ation Materia	als and				
			Estimated	1	Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Health and Safety	CO monitor	Each	1						
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.								
2 Labor	Labor	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									

#### **Measure 2** Infiltration Redctn

### Components

Inspected	

**Comment** Unable to isolate specific areas of air infiltration. Home appears generally leaky with probable wood plank walls, ceilings and floors.

- 1. Caulk and seal openings in subfloor in crawlspace prior to insuating
- 2. Seal all plumbing projections through floor in living space.
- 3. Repair loose ceiling tile in kitchen.
- 4. Foam seal Baloon Framing openings in crawlspace exterior walls.

	<u> </u>	Ü		Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

-	<i>Measure</i> 3 D	WH Pipe Insulation			Componen	ts			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Pipe Insulation	Each	1					
3	Other	DHW Pipe Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
		loor Ins. R-19 Il R19 fiberglass insulation.	2x8 joist,	24"oc.	Componen	<i>ts</i> Crawl	Space		Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	2100					
C	Other Detail			1					
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Client Name: Client ID: 15015SE-4179 Alt. Client ID: McMinn Work Order (Bid Form)
Work Order Name: WO/15015SE-4179/1

Report Run On: 4/29/2010

DOE Weatherization Assistant Version 8.6.0 Page 4 of 5

Measure 5 Prac (Wal	tice Lead Safe Weather ls)	ization		Componen	ts		ı	nspected
follow re Painting	pre-1978. Follow lead sa quirements of EPA Lead . Contractor to adhere to mining need for presence	-Based F 4 step re	Paint R quirem	enovation, fents of WA	Repair ar P ARRA rm	nd	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measure	e Sub Total:		] ;	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	